



Approved Valuer for immovable properties

foundation soil,

Machines , structural engineering and water

technologies.

Member working group iovrvf VSAB,
EMP Arbitrator High court of Kerala

Report: Structural Damage Assessment of 4- Storey Building with Swimming Pool

Executive Summary

A 4-storey building with a swimming pool on the top floor has suffered structural damage, resulting in wetness and cracks in the building's walls and foundation. This report assesses the damage and provides recommendations for repairs and mitigation measures.

Introduction

The 4-storey building, located in [Location], has a swimming pool on the top floor, which holds approximately 70,000 kilograms of water. The building's design and construction documents were reviewed, and a site inspection was conducted to assess the damage.

Observations and Findings

1. **Visual Inspection:** A visual inspection of the building revealed cracks in the walls, particularly on the top floor, and wetness in various areas. The cracks appear to be more pronounced near the foundation and lower floors.
2. **Structural Assessment:** A review of the building's design and construction documents indicates that the building's foundation and structural system may not have been designed to withstand the weight and vibrational loads induced by the swimming pool.
3. **Water Damage:** Water leakage from the swimming pool has caused damage to the building's walls, floors, and foundation.



Camp: Bethel
Koch Kadavanthra
Kochi - 682 020



alexthomasc77@gmail.com



9847942529, 9947117033

Recommendations

1. Immediate Repairs: Perform immediate repairs to the damaged areas, including sealing the water leaks and repairing the cracks in the walls and foundation.
2. Structural Reinforcement: Consider reinforcing the building's foundation and structural system to ensure it can withstand the weight and vibrational loads induced by the swimming pool.
3. Vibration Mitigation Measures: Implement vibration mitigation measures, such as installing vibration isolators or using vibration-damping materials, to reduce the transmission of vibrations from the swimming pool to the building's foundation.
4. Regular Maintenance: Regularly inspect and maintain the swimming pool and the building's structural system to prevent further damage.

Conclusion

The 4-storey building with a swimming pool on the top floor has suffered structural damage due to the weight and vibrational loads induced by the pool. Immediate repairs and structural reinforcement are necessary to prevent further damage and ensure the building's safety.

Action Plan

1. Perform immediate repairs to the damaged areas.
2. Engage with structural engineers to assess the building's foundation and structural system.
3. Implement vibration mitigation measures.
4. Regularly inspect and maintain the swimming pool and the building's structural system.

Prepared by Er.Alex Thomas

<https://www.graceconsult.in/>

Date:06/01/2025